



Electrical Machines

Total Marks : 50

Attempt All Questions.

Sketch neat and labeled diagrams.

-

Question No 1.

- A. Discuss any two methods of speed control each for series and shunt wound DC motors? (CLO – 3) 15
- B. Consider a 8 poles DC Generator, Number of conductors Z are 480, emf induced per conductor is 2.2V , current per conductor is 100A find the terminal voltage E , output current I and power generated for both lap and Wave windings ? (CLO – 1) 10
-

Question No 2.

- A. Determine Relationship between torque and armature current? (CLO – 2) 15
- B. Differentiate between lap winding and wave winding? (CLO – 3) 10
-

“GOOD LUCK”

Qno 1

A.

Speed Control of Dc Series Motor:


* Armature Resistance Control Method

* Field Divester Method

(1) Armature Resistance Control Method

Here the Controlling Resistance is connected directly in series with the supply of the motor

as shown:




This reduces the voltage available

across the armature and hence the speed falls. By changing the value of variable resistance

This method of speed control is most ~~also~~ economical for constant torque.

(2) Field Diverted Method:

This method uses a diverter. Here the ^{field} flux can be reduced by shunting a portion of motor current around the series field. Lesser the diverter resistance less is the field current. Less flux therefore more speed.




(2) Speed Control of DC Shunt motor

* Flux Control Method.

• In this method, a variable resistance (known as shunt field rheostat) is placed in series with shunt field winding as shown.

• An increase in controlling resistance reduces the field current with a reduction in flux and an increase in speed.




- (i) This is an easy and convenient method.
- (ii) It is an inexpensive method since very little power is wasted in the shunt field rheostat due to relatively small value of I_{sh} .

★ Armature Control Method :

This is done by inserting a variable resistance R_C (known as Controller Resistance) in series with the armature as shown.

The flux remain constant while armature current is changed ~~produce~~.
Produce change in speed



Large amount of power is wasted in the controller resistance since it carries full armature current I_a .

Q No 1

B.

Solution:

No of Conductor per path

$$\frac{480}{8} = 60$$

Terminal Voltage

$$= \text{emf per Conductor} \times \text{no of Conductor}$$

$$= 0.22 \times 60$$

$$= 13.2 \text{ V}$$

$$\Rightarrow \text{output Current}$$

$$= \text{Current per Conductor} \times \text{no of parallel path}$$

$$= 100 \times 8 = 800 \text{ A}$$

$$\Rightarrow \text{power generated for Lap winding}$$

$$= \text{output current} \times \text{generated EMF}$$

$$= 800 \times 13.2$$

$$= 10,560 \text{ W}$$

For wave winding

no of parallel paths = 2

no of conductor per path's

$$\frac{480}{2} = 240$$

$$\begin{aligned} \text{terminal voltage} &= 0.22 \times 240 \\ &= 52.8 \text{ V} \end{aligned}$$

output current

$$100 \times 2 = 200 \text{ A}$$

power generated for wave winding

$$= 200 \times 52.8$$

$$= 10,560 \text{ W}$$

Q No 2

A. Torque & Armature Current Relationship.

$$P_e = P_m$$

(P_e = Electrical power
 P_m = mechanical ")

$$P_e = E_a I_a$$

$$\text{as } (E_a = E_b + I_a R_a) \text{ kv}$$

$$P_e = (E_b + I_a R_a) I_a$$

$$P_e = E_b I_a + I_a^2 R_a$$

$$P_e = E_b I_a + I_a^2 R_a \text{ (as dissipate in form of heat)}$$

$$P_e = E_b I_a$$

Now

$$P_m = T \omega$$

$= T \omega$ (Torque in N·m
 and ω (angular speed
 in rad/sec)

$$1 \text{ radian} = 1/2\pi$$

$$\therefore \text{In RPM} = N \cdot 2\pi/60$$

$$= \text{rad/sec}$$

$$P_m = T \omega = T \cdot N \cdot 2\pi/60$$

$$P_m = P_e$$

$$E_b = \frac{P \cdot 2\pi \cdot N}{60 \cdot I_a}$$

$$T \cdot N \cdot 2\pi/60 = E_b I_a$$

$$T = \frac{P \cdot 2\pi \cdot I_a}{2\pi \cdot N}$$

Hence T is directly
 proportional to I_a

Q No 2

B. Differentiate lap winding and wave winding.

Basic for Comparison	Lap winding	Wave winding
i) Definition	The coil is lap back to the succeeding coil	The coil of the lap winding form the wave shape.
(ii) Connections	The end of the armature coil is connected to an adjacent segment on the commutators.	The end of the armature coil is connected to commutator segment distance a pole
(iii) Parallel path	The number of parallel paths are equal to the total of number poles.	The number of parallel paths is equal to two
(iv) Other name	Parallel winding or Multiple winding	Two-circuit or series winding
(v) EMF	less	More
(vi) Number of brushes	Equal to the number of parallel paths.	Two

	Basic for Comparison	Lap winding	Wave winding
(vii)	Types	Simplex and Duplex lap winding	Progressive and Retrogressive wave winding
(viii)	Efficiency	Less	High
(ix)	Additional Coil	Equalizer Ring	Dummy Coil
(x)	Winding Cost	High (because more conductor is required)	Low
(xi)	uses	In low voltage, high current machine	In high voltage low current machine